



State of Utah

Department of
Natural ResourcesMICHAEL R. STYLER
*Executive Director*Division of
Oil, Gas & MiningJOHN R. BAZA
*Division Director*JON M. HUNTSMAN, JR.
*Governor*GARY R. HERBERT
Lieutenant Governor

Representatives Present During the Inspection:

Company Russell Hardy

OGM Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0150007
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, November 20, 2007
Start Date/Time:	11/20/2007 8:00:00 AM
End Date/Time:	11/20/2007 1:00:00 PM
Last Inspection:	Tuesday, October 23, 2007

Inspector: Karl Houskeeper, Environmental Scientist IIIWeather: Clear/Windy, Temp. 42 Deg. F.Inspection ID Report Number: 1467Accepted by: dhaddock *dhaddock*
12/7/2007Permittee: **CONSOLIDATION COAL CO**Operator: **CONSOLIDATION COAL CO MID-CONTINENT REGION**Site: **HIDDEN VALLEY MINE**Address: **PO BOX 566, SESSER IL 62884**County: **EMERY**Permit Type: **PERMANENT COAL PROGRAM**Permit Status: **RECLAIMED**

Current Acreages

960.00	Total Permitted
6.70	Total Disturbed
6.70	Phase I
	Phase II
	Phase III

Mineral Ownership

- ☐ Federal
☐ State
☐ County
☒ Fee
☐ Other

Types of Operations

- ☒ Underground
☐ Surface
☐ Loadout
☐ Processing
☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit last renewed 1/29/2007. The permit area is 960 acres within T. 23 S. R. 6 E. W1/2 Sec 17 and all of Sec. 18. The Permittee's address is listed on the Reclamation Agreement [12755 Olive Blvd. St Louis Mo] has changed. The corporate headquarter's address should read [1800 Washington Rd., Pittsburgh PA]. The Engineering Office for the western operations is in Sesser, IL. Consolidation Coal Co. Board of Directors has authorized an exploratory engineering study at the Hidden Valley reclaimed site.

Inspector's Signature: _____

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Date Tuesday, November 20, 2007

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

Permit Number: C0150007

Inspection Type: PARTIAL

Inspection Date: Tuesday, November 20, 2007

Inspection Continuation Sheet

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

Permit last renewed 1/29/2007. The permit area is 960 acres within T. 23 S. R. 6 E. W1/2 Sec 17 and all of Sec. 18. The Permittee's address is listed on the Reclamation Agreement [12755 Olive Blvd. St Louis Mo] has changed. The corporate headquarter's address should read [1800 Washington Rd., Pittsburgh PA]. The Engineering Office for the western operations is in Sesser, IL. Consolidation Coal Co. Board of Directors has authorized an exploratory engineering study at the Hidden Valley reclaimed site.

2. Signs and Markers

The mine ID sign is in place and contains the required information.

4.d Hydrologic Balance: Water Monitoring

Samples were pulled September 19, 2007 from the upper and lower locations and have been entered into the EDI website. The information has not been uploaded. Additional samples were collected on August 19, 2007 from the new locations.